

Professional Series Portable Firmware R05.13.09 Customer Release Notes

NOTE: Professional CPS R06.09.06 or later must be used with this firmware.

This release of radio firmware only supports the Popular and Preferred families of Professional Series Portable Radios. All bands in these families are supported. For any questions, please contact Customer Resources at 1-800-927-2744.

I. Enhancements

None

II. Corrections

Item #1: Intermittent low audio in LTR

While operating on an LTR system in narrowband mode an older LVZIF design radio may exhibit low audio during a second reception while within the scan hang timer window.

Item #2: Radio lockup when switching to PassPort Zone

While changing Zones from a Conventional Zone to a PassPort Zone the PassPort option board would hang if the Conventional Zone was configured with Auto Scan and Priority 1.

III. Known issues

May 2, 2008

1

Item #1: Call Light not working with Option Board

The Call Light does not work when Option Board Type is set to Simple Option Interface/Advanced Option Interface.